

Printing up a Material List.

In Pocket DLog on the Recon,

1. Open Pocket Dlog, click on FILE / MATERIAL LIST
2. Click on Make File, nothing visible will happen but a file was created and saved within the project folder in LOGPROJECTS.
3. Go through the steps on transferring data from the Recon (Handheld) to you desktop PC.
4. Now on your desktop double left click on My Computer.
5. Double Left click on Local Disk C:/
6. Double left click on Tile Maps. (or where your data is saved)
7. Double click on the folder with the project name that you want the material list for. Go to the right hand screen and double click on the material list icon.
8. You should now see a page with your material list on it.
9. Now left click the File button at the top of the screen, and left click on PRINT.
10. A box should appear to print click OK at the bottom.